

## TECHNICAL TOPICS

### BODY/CHASSIS



#### Rattle Noise From Under The Vehicle

18-21MY Range Rover, RR Sport  
19-21MY Discovery

##### Customer Voice:

- A customer may report a rattle type noise from under the vehicle with the engine running.

##### Technical Description:

- The noise may be traced to the engine under-shield. The star washers that retain the sound absorber mat to the under-shield may have relaxed and not maintained proper clamping force.

##### Status:

- TSB JLRTB02065NAS1 will be published to address this concern by replacing the star washers with speed nuts to better clamp the damper pad.

