



Technical Service Bulletin

96 Lane change assist, DTC U112200 (1188157) is stored in the lane change assistance control module

96 20 60 2061819/1 December 18, 2020.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2021 – 2023	All	Lane change assist

Condition

Workshop findings:

The following DTC is stored in the lane change assistance control module, J769 (address word 003C):

- **DTC U11220** (data bus, implausible message) with symptom code 1188157.

Technical Background

Diagnosis deviation in lane change assistance control module, J769 (address word 003C).

Production Solution

Not applicable.

Service


No repair is necessary, as this DTC does neither cause any restrictions in functionality nor any malfunction messages visible to the customer.

Do not perform any repairs. Any repairs for this concern may be denied.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information



Technical Service Bulletin

All part and service references provided in this TSB (2061819) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2020 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.