

Classification:

EL12-047a

Reference:

ITB12-043a

Date:

December 15, 2020

COPYRIGHT© NISSAN NORTH AMERICA, INC.

2012 QX56; DOOR REQUEST SWITCH INOPERABLE AND NO START AT PDI

APPLIED VEHICLES: 2012 QX56 (Z62)

APPLIED VINS & DATES: 2WD built between:
JN8AZ2NF(*)C9 517709 and JN8AZ2NF(*)C9 518052 // Apr. 2, 2012 – May 7, 2012
JN8AZ2ND(*)C9 716094 and JN8AZ2ND(*)C9 716214 // Apr. 2, 2012 – Apr. 27, 2012
AWD built between:
JN8AZ2NE(*)C9 019978 and JN8AZ2NE(*)C9 020999 // Apr. 2, 2012 – May 7, 2012
JN8AZ2NC(*)C9 316943 and JN8AZ2NC(*)C9 317302 // Apr. 2, 2012 – Apr. 27, 2012

This bulletin is no longer active.

Please discard previous versions of ITB12-043.

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
July 31, 2012	ITB12-043	Original bulletin published
December 15, 2020	ITB12-043a	Bulletin no longer active

Infiniti Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Infiniti retailer to determine if this applies to your vehicle.