



Bulletin No.: PIT5777A
Published date: 12/3/2020

Preliminary Information

PIT5777A False Check Reverse Lamps Message On DIC / No DTCs

Models

Brand:	Model:	Model Years:	VIN:		Engine:	Transmissions:
			from	to		
Chevrolet	Suburban	2021	All	All	All	All
Chevrolet	Tahoe	2021	All	All	All	All

Involved Region or Country	North America
Condition	Some customers may comment on a Check Reverse Lamp message on the DIC. The reverse lights will still be operational and there will be no DTC's.
Cause	This concern could be caused by a calibration issue with the K219 Lighting Control Module.

Correction:

Engineering has released an update calibration to correct this concern. Reprogram the K219 Lighting Control Module with the latest calibrations listed in Tis2Web.

Warranty Information

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

Labor Operation	Description	Labor Time
2811105	K219 Lighting Control Module Reprogramming with SPS	Use Published Time

Additional SI Keywords

back up backup bulb light lights

Version History

Version	2
Modified	09/18/2020 - Created on. 12/03/2020 - Updates to the Warranty and Correction sections.



GENERAL MOTORS