

## **Service Bulletin**

Bulletin No.: 20-NA-028

Date: December, 2020

## **INFORMATION**

Subject: Charge Air Cooler Icing During Extreme Cold Weather Conditions

| Brand:    | Model:                 | Model Year: |      | VIN: |    | Engine   | Transmission: |
|-----------|------------------------|-------------|------|------|----|--|---------------|
|           |                        | from        | to   | from | to | Engine:  | iransmission: |
| Buick     | Encore GX<br>(VIN M)   | 2020        | 2021 |      |    | Equipped with<br>1.2L or 1.3L<br>Engine (RPOs<br>LIH, L3T) |               |
| Chevrolet | Trailblazer<br>(VIN M) | 2021        | 2021 | _    |    | Equipped with<br>1.2L, 1.3L<br>Engine (RPOs<br>LIH, L3T)   |               |

| Involved Region or Country | North America |
|----------------------------|---------------|
|----------------------------|---------------|

The purpose of this bulletin is to notify dealership personnel, as well as providing the customer with the usage instructions from the owner manual, that in extreme cold weather (-18°C or less / 0°F or less), a grille winter cover needs be added during PDI to avoid the customer returning with concerns related to charge air cooler icing.

For Canadian vehicles, the cover should be included with your vehicle. Order a cover if it is missing and install the winter cover per the owner manual usage instructions.

## **Encore GX**

Refer to the service video shown above for installing the Winter Grille Cover.

**Note:** Clean the surface before installing the Winter Grille Cover.

## **Warranty Information**

For vehicles repaired under the Bumper-to-Bumper coverage (Canada Base Warranty coverage), use the following labor operation. Reference the Applicable Warranties section of Investigate Vehicle History (IVH) for coverage information.

| Labor<br>Operation | Description                           | Labor Time |  |
|--------------------|---------------------------------------|------------|--|
| 1086278*           | Winter Grille Cover<br>Installation** | 0.2 hr     |  |

<sup>\*</sup>This is a unique Labor Operation for bulletin use only.

<sup>\*\*</sup>Installation perform is a one time charge only.

| Version  | 4  |
|----------|--|
|          | Released February 7, 2020  |
| Modified | July 9, 2020 – Added the 2021 Trailblazer, included an Encore GX video and added information for Canada. |
|          | September 29, 2020 – Added a Warranty Information section.   |
|          | December 1, 2020 – Added the 2021 Model Year to Encore GX.   |