Model Series 167: Cracks In ARTI-CO Seat Cushion Cover On Front Seat

Topic number LI91.18-P-071629
Version 2

Function group 91.18 Seat covers

Date 10-30-2020

Validity Model series 167 ARTICO man-made leather upholstery

or ARTICO man-made leather upholstery/DINAMICA mi-

crofiber

Reason for change Model series, identified equipment and remedy changed.

Reason for block

Complaint:

The seat cushion cover on the front seat cracks when side bolster is equipped with "ARTICO man-made leather upholstery".

For vehicles equipped with "ARTICO man-made leather upholstery/DINAMICA microfiber - black (601A)", please create a PTSS case straight away.

Note: This is the seat covering with NO PERFORATIONS in the man-made leather

Attachments	
File	Description
example1.jpg	Example 1
example2.jpg	Example 2
example3.jpg	Example 3

Cause:

If this complaint occurs with the "ARTICO man-made leather upholstery/DINAMICA microfiber - black (601A)" which has NO PERFORATIONS, open a PTSS case with the following information:

- + Images of the seat cover
- + Images of the seat cushion padding (foam)
- + Manufacturing date of the seat cushion cover
- + Mileage

Remedy:

Replace seat cover.

Symptoms
Body / Seat / Seat cover / Chafed through
Body / Seat / Seat cover / Detaches

XENTRY TIPS

Operation numbers/damage codes						
Op. no.	Operation text	Time	Damage code	Note		
			91A04 07			
			91N04 07			

Validity				
Vehicle	Engine	Transmission		
GLE (167)	*	*		
GLS (167)	*	*		

Attachments

example1.jpg:



example2.jpg:



example3.jpg:

