



Technical Journal

TITLE:

PSCM ghost codes U230057 / U112B87

REF NO: TJ 35774.1.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2020-11-24	STATUS DATE: 2020-12-03
FUNC GROUP: 6422	FUNC DESC: Steering gear, servo complete	Page 1 of 2	

“Right first time in Time”

DESCRIPTION:

If workshops find DTC’s PSCM-U230057 and PSCM-U112B87 in the vehicle, please follow the advice under Service.

Work is ongoing to solve the issue, a new software is scheduled for 2021 week 04.

CSC Customer Symptom Codes

Code	Description
3L	Technician information/Repair information/Not for warranty use

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
PSCM	U230057	Permanent
PSCM	U112B87	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	ED	E400V6					2021-2021		0439208-9999999	202037-202103

**SERVICE:**

Please ignore the DTC's PSCM-U230057 and PSCM-U112B87 since they cause no steering symptoms for customer, nor do they give any warning messages in the car.

The codes cannot be erased with VIDA, so there is no need to fault trace them further until the new software is available.

Warranty claim info:

No warranty claim accepted for a job described in this TJ.

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 6422.