



Technical Journal

TITLE:

Oxygen sensor thread repair methodREF NO:
TJ 35818.1.1ISSUING DEPARTMENT:
Technical ServiceCAR MARKET:
United States and CanadaPARTNER:
3 US 7510 Volvo Car USAISSUE DATE:
2020-12-15STATUS DATE:
2020-12-21FUNC GROUP:
2544FUNC DESC:
Lambda sond system**Page 1 of 3****“Right first time in Time”**

Attachment

File Name	File Size
Cutting fluid.png	0.0838 MB
Heli Coil O2 Thread repair kit.png	0.2254 MB

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

There is a new repair method listed in VIDA for reconditioning the oxygen sensor thread if they are damaged upon removal.

CSC Customer Symptom Codes

Code	Description
DL	Warning lights and chimes/Malfunction Indicator Light ("Check engine" light) indication/no indication

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
1XX							0-0		-	0-0
2XX							0-0		-	0-0
3XX							0-0		-	0-0
5XX							0-0		-	0-0
XXX							0-0		-	0-0



SERVICE:

Follow VIDA instructions:

**Overhaul instructions/ Engine with mountings and equipment/ 25 intake and Exhaust systems/
Catalytic Convertor**

See Example of Heli coil kit that can be ordered thru an aftermarket supplier (Amazon, tool dealer, parts store)

VST Operation Number

VST Operation Number	Description
25443-3	Catalytic convertor reconditioning

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service instruction described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 2544.

To view TJ attachments continue to next page. This TJ has two attachments.



Helicoil 4833 Oxygen Sensor Thread Repair Kit M 18 x 1.5

