

GLOBAL SAFETY FIELD INVESTIGATIONS
DCS5610
URGENT - DISTRIBUTE IMMEDIATELY

Date: December 14, 2020

Subject: N202318400 - Service Update
Warped Trailer Hitch Cover – US and Canada Only

Models: 2020 Chevrolet Blazer

To: All General Motors Dealers

General Motors is releasing Service Update N202318400 today. The total number of U.S. vehicles involved is approximately 1,932. Please see the attached bulletin for details.

Global Warranty Management (GWM)

The Required Field Action section on the Investigate Vehicle History (IVH) screen will be updated December 15, 2020 or sooner. A list of involved vehicles in dealer new inventory is attached to this message. Please hold all warranty transactions until IVH has been updated.

END OF MESSAGE
GLOBAL SAFETY FIELD INVESTIGATIONS

Service Update

N202318400 Warped Trailer Hitch Cover – US and Canada Only



Release Date: December 2020

Revision: 00

Attention: This service update includes vehicles in dealer inventory and customer vehicles that return to the dealership for any reason. This bulletin will expire at the end of the involved vehicle's New Vehicle Limited Warranty period.

Make	Model	Model Year		RPO	Description
		From	To		
Chevrolet	Blazer	2020	2020		

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	In certain 2020 model year Chevrolet Blazer vehicles, the rear trailer hitch cover may be warped and loose. A rattling noise may occur, and in some cases, the cover may fall off of the vehicle.
Correction	Dealers are to inspect the rear bumper fascia trailer hitch cover and replace if necessary.

Parts

Quantity	Part Name	Part No.
1	Rear Bumper Fascia Trailer Hitch Access Hole Cover	84888905

It is estimated that there are only 2,102 involved vehicles that will require parts being replaced. **Due to the small number of vehicles anticipated that will need this repair and the limited initial parts availability, dealers are encouraged not to order these parts for use as shelf stock.**

Reminder: Parts may be removed from Retail Inventory Management (RIM). Dealers should review the affected parts to confirm RIM managed status. Parts may have quantity limiters in effect.

Warranty Information

Labor Operation	Description	Labor Time	Trans. Type	Net Item
9105471	Inspect Rear Bumper Fascia Trailer Hitch Access Hole Cover	0.1	ZFAT	N/A
	ADD: Replace Rear Bumper Fascia Trailer Hitch Access Hole Cover	0.1		

Service Procedure

Inspect the rear bumper fascia trailer hitch cover:

1. If the rear bumper fascia trailer hitch access hole cover does not sit flush with the fascia or is loose, replace the rear bumper fascia trailer hitch access hole cover. Refer to *Rear Bumper Fascia Trailer Hitch Access Hole Cover* in SI.
2. If the rear bumper fascia trailer hitch access hole cover sits flush and is secure, no further action required.

Dealer Responsibility

Whenever a vehicle subject to this service update enters your vehicle inventory or is in your facility for service in the future, and the vehicle is still covered under the New Vehicle Limited Warranty, you must take the steps necessary to be sure the service update correction has been made before selling or releasing the vehicle.

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this bulletin must be held and inspected/repared per the service procedure of this bulletin before customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Service Update

N202318400 Warped Trailer Hitch Cover



Dealer Reports

The Inventory tab of the Open Vehicle Report will contain Service Update Bulletin VINs that apply to this field action. This information is intended to assist dealers with the **PROMPT COMPLETION** of these vehicles. The Customer In-Service tab will not contain Service Update Bulletin VIN data because the intent of a Service Update Bulletin is to not inconvenience a customer with a special trip for service. Service Update Bulletins are to be completed when the customer is in for a regularly scheduled visit.

GM bulletins are intended for use by professional technicians, NOT a "do-it-yourselfer". They are written to inform these technicians of conditions that may occur on some vehicles, or to provide information that could assist in the proper service of a vehicle. Properly trained technicians have the tools, equipment, safety instructions, and know-how to do a job properly and safely. If a condition is described, DO NOT assume that the bulletin applies to your vehicle, or that your vehicle will have that condition. See your dealer for information on whether your vehicle may benefit from the information.



**We Support
Voluntary Technician
Certification**