

Subject: Engineering Information – Roof Panel Joint Finish (Ditch) Molding Loose and/or Lifted

This EI has been revised to end the need for information from the field. Please discard PIE0551.

| Brand: | Model: | Model Year: | | VIN: | | Engine: | Transmission: |
|-----------|--------|-------------|------|------|----|---------|---------------|
| | | from | to | from | to | | |
| Chevrolet | Sonic | 2016 | 2019 | — | — | — | — |

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

| | |
|-----------------|--|
| Version | 2 |
| Modified | Released December 20, 2019 December 11, 2020 – Ended the need for further information from the field. |