

Subject: Engineering Information - Slow Start and/or No Start, Battery Message Indicated, Having to Jump Start On More Than One Occasion

This PI has been revised to end the need for information from the field. Please discard PIE0578B.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
GMC	Sierra 1500	2020	2020	-	-	All	All

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	4
Modified	Released August 04, 2020 Revised August 06, 2020 – Revised to update the Correction. Revised September 22, 2020 – Revised to update Steps 8, 9 and 10. Revised December 17, 2020 – Ended the need for further information from the field.