



# Service Bulletin

Service Bulletin - Technisches Rundschreiben - Circulaire Technique - Circular Tecnica

Date: 10 July 2020

Subject: Wiring repositioning

Product: Brutale 1000 Serie Oro from vin ... LV000011 to vin ... LV000130  
excluding the attached list:

ZCGLFTW0LV000093	ZCGB710ABLV000106	ZCGB710ABLV000116	ZCGB710ABLV000121
ZCGB710ABLV000094	ZCGB710ABLV000107	ZCGB710ABLV000117	ZCGLFTW2LV000127
ZCGB710ABLV000095	ZCGB710ABLV000109	ZCGB710ABLV000118	ZCGLFTW4LV000128
ZCGB710ABLV000096	ZCGB710ABLV000114	ZCGB710ABLV000119	ZCGLFTW6LV000129
ZCGB710ABLV000097	ZCGB710ABLV000115	ZCGB710ABLV000120	

Following continuous monitoring of the quality of our product, it has been found that for the Brutale 1000 Serie Oro motorcycle you purchased, it may have the branch of the wiring directly to the side stand switch \ oil pressure sensor not positioned correctly with respect to the oil pan protection cover.

We kindly ask you to reposition the cables BEFORE delivering the vehicle to the final customer during the pre-delivery phase. For the motorcycles already sold, we ask you to reposition the cable during a maintenance service or on the first useful occasion at your workshop.

## NON-CONFORMING PART IDENTIFICATION PROCEDURE:

It will be possible to identify the incorrect position of the branch of the wiring in question by observing, on the left side of the motorcycle, the branch of the system directed to the side stand switch and oil pressure sensor; it is necessary that the indicated wiring branch is NOT pressed by the oil pan protection cover. The possible incorrect positioning (on the left) and the correct positioning (on the right) are shown below;



Thanking you in advance for your collaboration, we remain at your disposal for any technical / commercial support.

Kind regards  
MV AGUSTA MOTOR S.p.A.  
Technical Assistance Service