



**NUMBER:** 08-077-20

**GROUP:** 08 - Electrical

**DATE:** August 29, 2020

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**This bulletin supersedes Service Bulletin 08-122-19, dated December 06, 2019, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight updates.**

***SUBJECT:***

Additional Repair Steps After the Steering Gear or Pump was Replaced

***OVERVIEW:***

This bulletin has been canceled. When performing repairs on the steering gear or Electric Hydraulic Power Steering (EHPS) pump, follow published service manual procedures in DealerCONNECT/Service Library.

***MODELS:***

2018 - 2019

(JL)

Jeep Wrangler

**NOTE: This bulletin applies to vehicles within the following markets/countries: North America, APAC, LATAM and EMEA.**

**NOTE: This bulletin applies to vehicles equipped with Long Wheel Base (Sales Code 595).**

***POLICY:***

Information Only