



STAR ONLINE PUBLICATION

Case Number: S1905000008

Release Date: 06/03/2020

Symptom/Vehicle Issue: ABS Active DTC C006A-49 Multi-Axis Acceleration Sensor-Internal Electronic Failure

Discussion:

Note- check for service bulletins and software updates prior to performing any other repairs for this dtc.

After performing service bulletin and module update if the code returns, proceed to the Service Diagnostic for DTC C006A-49, if the active code clears no further repairs are required. If the code does not clear, follow the service diagnostic test procedures as detailed in all steps. Replacing ABS or ORC modules is not necessary to correct this DTC if the active code clears.

This document does not authorize warranty repairs. This communication documents a record of past experiences. STAR Online does not provide any conclusions about what is wrong with the vehicle. Rather, it captures all previous cases known that appear to be similar or related to the vehicle symptom / condition. You are the expert, and you are responsible for deciding on the appropriate course of action.

Contact STAR Center, or your Technical Assistance Center Via TechCONNECT or eCONTACT ticket if no solution is found