



NUMBER: 08-098-20

GROUP: 08 - Electrical

DATE: October 13, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Technical Service Bulletin (TSB) 08-002-19 REV. A, date of issue October 08, 2019, which should be removed from your files. This is a complete revision and no asterisks have been used to highlight revisions.

SUBJECT:

UCQ Radio Enhancements

OVERVIEW:

This bulletin has been canceled. The software on the Uconnect site will be turned off. Any USB flash drives that has this software on it must be deleted. If the radio is updated with 28.3 software it may cause more issues with the radio and dissatisfy the customer. Enhanced software should be available the first quarter of 2021.

MODELS:

2018 (JL) Jeep Wrangler

NOTE: This bulletin applies to vehicles within the following markets/countries: Canada.

NOTE: This bulletin applies to vehicles equipped with an Uconnect 8.4 navigation radio

(Sales Codes UCQ).

POLICY:

Information Only.