



NUMBER: 18-002-20 REV. C

GROUP: 18 - Vehicle Performance

DATE: November 13, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Technical Service Bulletin (TSB) 18-002-20 REV. B, date of issue September 16, 2020, which should be removed from your files. All revisions are highlighted with **asterisks**** and include new RRT number and updated build date.**

This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) **20-086, date of issue November 13, 2020.**** All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.**

SUBJECT:

Flash: Powertrain Control Module (PCM) Updates - AN-K8-18-20201002

OVERVIEW:

Refer to China Joint Venture (JV) released document AN-K8-18-20201002, for details on this service action.

MODELS:

2019 (K8) Jeep Grand Commander (China)

NOTE: This bulletin applies to vehicles within the following markets/countries: APAC (China only).

NOTE: This bulletin applies to vehicles built on or before **December 31, 2019 (MDH 1231XX)**** equipped with a 2.0L I4 DOHC Direct Injected (DI) Turbo Engine W/ESS (Sales Code EC1).**

Policy:

Information Only