



**NUMBER:** 18-001-20 REV. B

**GROUP:** 18 - Vehicle Performance

**DATE:** November 13, 2020

*This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.*

**This bulletin supersedes Technical Service Bulletin (TSB) 18-001-20 REV. A, date of issue September 22, 2020, which should be removed from your files. All revisions are highlighted with **\*\*asterisks\*\*** and include new RRT number and updated build date.**

**This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) **\*\*20-085, date of issue November 13, 2020.\*\*** All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.**

***SUBJECT:***

Flash: Powertrain Control Module (PCM) Updates - AN-K4MCA-18-20201001

***OVERVIEW:***

Refer to China Joint Venture (JV) released document AN-K4MCA-18-20201001, for details on this service action.

***MODELS:***

2019 (K4) Jeep Cherokee (China)

**NOTE: This bulletin applies to vehicles within the following markets/countries: APAC (China only).**

**NOTE: This bulletin applies to vehicles built on or before **\*\*December 09, 2019 (MDH 1209XX)\*\*** equipped with a 2.0L I4 DOHC Direct Injected (DI) Turbo Engine W/ESS (Sales Code EC1).**

***Policy:***

Information Only