



NUMBER: 18-080-20 REV. A

GROUP: 18 - Vehicle Performance

DATE: November 26, 2020

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Technical Service Bulletin (TSB) 18-080-20, date of issue September 09, 2020, which should be removed from your files. All revisions are highlighted with **asterisks**** and include converting to an Rapid Response Transmittal (RRT) and build date change.**

****This Technical Service Bulletin (TSB) has also been released as a Rapid Response Transmittal (RRT) 20-091, date of issue November 26, 2020. All applicable Sold and Un-Sold RRT VINs have been loaded. To verify this RRT service action is applicable to the vehicle, use VIP or perform a VIN search in DealerCONNECT/Service Library. All repairs are reimbursable within the provisions of warranty. This RRT will expire 18 months after the date of issue.****

SUBJECT:

Flash: Powertrain Control Module (PCM) Updates - AN-K4MCA-18-20201101

OVERVIEW:

Refer to China Joint Venture (JV) released document AN-K4MCA-18-20201101, for details on this service action.

MODELS:

2020 (K4) Jeep Cherokee (China)

NOTE: This bulletin applies to vehicles within the following markets/countries: APAC (China only).

NOTE: This bulletin applies to vehicles built on or before ****November 17, 2020 (MDH 1117XX)**** equipped with a 2.0L I4 DOHC Direct Injected (DI) Turbo Engine W/ESS (Sales Code EC1).

Policy:

Information Only