

GPOP - Issue Review System

Part Number: 6XL47BD3A\$, 6XL47LT5A\$, 6XL48BD3A\$, 6XL48LT5A\$, 6XL57BD3A\$, 6XL57LT5A\$, 6XL58BD3A\$, 6XL58LT5A\$, 6XL81TU6A\$, 6XL82TU6A\$, 6XL85TU6A\$, 6XL86TU6A\$, 6XL91BD3A\$, 6XL91LT5A\$, 6XL92BD3A\$, 6XL92LT5A\$, 6XU26BD3A\$, 6XU26HL1A\$, 6XV32BD3A\$, 6XV32HL1A\$, 6XV33BD3A\$, 6XV33HL1A\$, 6XX37BD3A\$, 6XX37HL1A\$, 6XX38BD3A\$, 6XX38HL1A\$, 6XY28BD3A\$, 6XY28HL1A\$, 6XY29BD3A\$, 6XY29HL1A\$, 7BA61BD3A\$, 7BA61HL1A\$

Part Description: COVER, Front seat cushion / Rear seat cushion

Issue If there is tenting present on the seat cushion cover of the front or rear seats please
Description: DO NOT REMOVE THE TRIM COVER.

Please contact FCA Redacted Content. If no response, please leave a message and send an e-mail to FCA Redacted Content.

If no response in 15 minutes, proceed with repair. If tenting is present and removal of the trim cover is required, please remove the complete foam (w/OCS - Front Seats) and trim assembly by unclipping the attachments to the frame.

~ _____ ~
Contact us at CAGRIS@Chrysler.com for feedback related ONLY to this GPOP Tech Tip. Please include the Part Number(s) and Tech Tip Part Description of the Tech Tip you are referencing for our tracking system.

