

**01-18-16TT – MIL/EPC Lamp ON, DTC U300100 after a Charging System Concern, Discharged Battery or Battery Replacement**

Release date: 01/15/2021

Condition

ATTENTION:**THIS IS A TECH TIP, NOT A TECHNICAL BULLETIN.****TECH TIPS ARE NOT ASSOCIATED WITH WARRANTY CLAIMING.**

Applicable Vehicles

Model(s)	Year	Eng. Code	Trans. Code	VIN Range From	VIN Range To
Tiguan LWB, Passat, Beetle	2018-2020	2.0L (DDSA, DDSB, DGUA)	All	All	All

Revision Table

Instance Number	Published Date	Version Number	Reason For Update
2053316/2	1/15/21	01-18-16TT	Update model year applicability
2053316/1	12/14/18	TT 01-18-16	Original publication.

Technical Background

You may find a U300100: Control Module Improper Shutdown setting in the Engine/Motor Control Module -J623- after a battery related concern.

Service

- Enable transport mode.
- Disable transport mode.
- Clear fault through control module OBD with the engine off.
- Reevaluate the concern and the faults setting.

Additional Information

© 2021 Volkswagen Group of America, Inc. All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Volkswagen Group of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.