



# Technical Service Bulletin

## PSS 90 Instrument cluster clock and trip odometer reset to midnight or zero

90 21 85 2060249/4 January 15, 2021. Supersedes Technical Service Bulletin Group 90 number 20-76 dated October 16, 2020 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2020 - 2021	All	FPK

## Condition

REVISION HISTORY		
Revision	Date	Purpose
4	-	Revised <i>Service</i> (Updated expected software release date)
3	10/17/2020	Revised header (Added MY21 vehicles)
2	09/30/2020	Revised header (Updated vehicles)

### Customer states:

The clock and trip odometer sporadically reset to midnight or "0:00" (Figure 1).



Figure 1. The clock and trip odometer reset to 0 or 0:00.

## Technical Background

A shutdown issue leads to the cluster resetting itself sporadically.



# Technical Service Bulletin

---

## Production Solution

This bulletin will be updated when more information is available.

## Service

1. Explain to the customer that a solution is forthcoming for the end of the 1st quarter of 2021 and that no repairs are necessary at this point. Do not replace any components for this condition since this will not resolve the customer's concern.
2. Create a PSS record in the PSS application through the Pending Service Solutions (PSS) link in AccessAudi (under *Related Links >> Service*), or through the Technical Assistance page in Elsa.

## Warranty

This TSB is informational only and not applicable to any Audi Warranty.

## Additional Information

All part and service references provided in this TSB (2060249) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.