

Perform OTA Update Before Replacing PCM/ECM

AFFECTED VEHICLES

Year	Model	Trim Level
2021	TLX	ALL
2019-21	RDX	ALL

It has been found that when replacing the PCM/ECM, the Dynamic Drive mode images - normally displayed on the center display - no longer appear. In order to prevent this, make sure that the software version on the infotainment control unit reads **D.1.5.1** or higher. If the version is not up to date, you must complete the update by using the OTA function or via USB.

NOTE: If you are unable to complete the update, please create a Tech Line Contact and set System Group to Audio.