

Cracked Screen on Center Display?

AFFECTED VEHICLES

Year	Model	Trim
2018-21	Accord	ALL
2019-21	Insight	ALL
2018-21	Odyssey	Except LX
21019-21	Passport	Except Sport
2019-21	Pilot	Except LX

We have received information from the vendor (Alpine) that display panels are being replaced for cracks on the center display screen. When they review these parts, they're finding that an aftermarket screen protector had been installed and that the screen protector is cracked.

So, if you have a center display that appears to have a cracked screen, confirm that it does not have an aftermarket screen protector installed. If installed, remove it, and then check if the center display screen itself is cracked.