

## A/C Leaks Due to Bulkhead Insulator Fibers

### AFFECTED VEHICLES

Year	Model	Trim
2017-20	CR-V	ALL

Before replacing a compressor or discharge hose for pressure leaks or not blowing cold, verify that no fibers are found on the O-rings section of the hose at the bulkhead of the vehicle.

If found, remove the fibers and replace the O-rings, then recharge the A/C system.

