

SSM 49433 - 2020-2021 Explorer/Aviator/Police Interceptor Utility – Illuminated ABS Warning Lamp - DTCs C0031, C0034, C0037, And/Or C003A

Some 2020-2021 Explorer/Aviator/Police Interceptor Utility vehicles may exhibit an illuminated anti-lock brake system (ABS) warning lamp with diagnostic trouble codes (DTCs) C0031, C0034, C0037, and/or C003A. This may be due to metal contamination on the wheel speed sensors or wheel speed sensor rings. Verify that all wheel speed sensors and wheel speed sensor rings are free of metal contamination before replacing them. Refer to Workshop Manual (WSM), Section 206-09 for diagnostics.

APPLICABLE VEHICLES

2020 - 2021 CAR: TV U611N AVIATOR

2020 - 2021 CAR: TW U625N EXPLORER