



### **Incorrect Data on Door Label Set**

**Description:**

A few trucks left the factory with incorrect weight related data on the door labels.

**Corrective Action:**

Remove existing door label set and replace with the new set provided to the dealer at No Charge.

**UCHP SCC CODE:** S7552

**EXPIRATION DATE:** 1/31/2022

**CAUSAL PART NUMBER:** 84811608

**UCHP Labor Code:**

1720-16-09-01, Qty. 3 @ .1hr = .3hr Total

**PARTS MARKUP:** NA

**PARTS LIST:**

Label Sets sent to each dealer at No Charge.

**FOR MORE INFORMATION, CONTACT:** Terry Isley

[Terry.Isley@Volvo.com](mailto:Terry.Isley@Volvo.com)