

Volvo Chassis - Redundant Brake Switch Test - Code MID136 SID55 FMI2, or(DTC) P1055



> Internal Content

For a Volvo Chassis with a (Possible LOSS of Cruise Control Symptom or ABS Code MID136 SID55 FMI2, DTC P1055 being generated) Refer to the Redundant Brake Switch " TEST " information [here](#) and the Brake Micro Switch " ADJUSTMENT " procedure found in the Trucks Dealer Portal under the Service Tab - Tech Support - Tech Support Tips - FG-36 ; Different Methods Required When Adjusting The Brake Micro Switch TT 010 - 2015 [here](#).

Tags

[p105594](#) [k17291048](#) [p1055-94](#)

[mid 136 sid 55 fmi 2](#)

Related links and attachments

[TT-010-2015 Brake Micro Switch](#)

[Brake switch contacts test](#)



Feedback

[Give feedback](#)

to help improve the content of this article