

Diagnostic Code (DTC) B105254 Active And Unable To Be Cleared - Vehicles Manufactured On Or After 1 January 2021



Certain vehicles manufactured on or after 1 January 2021 may be found to have DTC B105254 active when codes are checked via the instrument cluster or a DTC readout is performed using Premium Tech Tool (PTT). For affected vehicles, B1052 will be present at the time the vehicle is delivered from the factory.

If B105254 is found to be active on a vehicle manufactured during the applicable date range:

At this time, no action should be taken to diagnose or repair this code.

- This has been determined to be a software issue. The code is not indicative of an existing problem and will not affect vehicle operation.
- B105254 will not illuminate the Malfunction Indicator Lamp (MIL), and the code will only be found by reviewing codes via the cluster or PTT.

This issue will be resolved by a software update which is currently in development. More information will be released as it becomes available.



Tags

[volvo](#)

[mack](#)

[b105254](#)

[b1052-54](#)

Related links and attachments

No links or attachments available



Feedback

[Give feedback](#)

to help improve the content of this article