

WLL2 Workshop campaign - Subsequent work on mounting for catalytic converter

Version 1

WLL2 Workshop campaign - Subsequent work on mounting for catalytic converter

Overview

There is a possibility that the screw contact surface on the transmission housing for the mounting of the catalytic converter was not modified according to specifications on the affected vehicles.

This results in is a misalignment or tension between the holder of the catalytic converter and the screw contact surface on the transmission housing. This can cause loosening of the threaded joint over the service life of the vehicle.

To prevent noises from the area of the transmission resulting from this, subsequent work is required on the mounting of the catalytic converter on the transmission housing.

Please arrange for this measure to be carried out on the affected vehicles during the next workshop visit or before handing the vehicles over to customers.

Model type	Cayenne Turbo (9YA) / Cayenne Turbo Coupé (9YB)
Model year	2020
Number	19

Parts required

Part No.	Designation	Quantity/vehicle	Parts return*
PAF01167026	Washer 8.4 x 24 x 2	2 ea.	No
PAF901076	Washer 8.2 x 18 x 2	2 ea.	No

* The parts must be stored until such time as the **related warranty or campaign claim has been credited**. If a **barcode is generated** with the credit note, the affected part must be sent to Porsche AG as usual. If no barcode is generated with the credit note, the part can go directly into the genuine remanufactured parts process or be scrapped.

Ordering required parts

Please order parts as needed.

Warranty processing

Validity:

This workshop campaign will be carried out up to 12/2/2025 and will be closed by the specified date. Please note that warranty claims can only be processed before this date.

Scope 1: Subsequent work on catalytic converter mounting

Damage Code	WLL2 / 66 000
Repair Code	2
Working time	225 TU

Please enter the campaign that was carried out in the Warranty and Maintenance booklet for the vehicle.

Porsche Mobility

If requested, the mobility of the affected customer can be assured by offering a suitable replacement vehicle.

Please invoice this additional service with the campaign scope via WWS.

Further information

Work instruction	TI No. 181/20, Group 2, Service, WLL2
Vehicle list and allocation	See PCSS or attached list for reference
Technical Information	See PCSS or Aftersales Document Database for reference

[WLL2 VIN List.xlsx](#)

8.6 KB

(85 views)

Created by [Ryan Cooney](#) on Jan 15, 2021 10:24 PM. Last modified by [Ryan Cooney](#) on Jan 15, 2021 10:31 PM.

699 Views [Report Abuse](#)

Categories: Workshop Campaigns, Cayenne

Tags : [cayenne](#), [9ya](#), [workshop campaign](#), [9yb](#), [year_l](#), [wll2](#)

Content and Topics

Your Groups >

Your Content >

Your Places >

Personal

Edit Profile >

Change Password >

Manage

Admin Console >

PPN Administration >

Create

Discussion >

Files >

Document >

Collaboration >

Document

Blog Post >

- Poll >
- Event >
- Photo Album >
- Idea >
- Space >
- Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. 009