

Technical Service Bulletin

70 Front hood noise insulation is missing

70 21 71 2061954/1 January 20, 2021.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q5, SQ5	2021 - 2023	All	Not Applicable
Q5 Sportback	2022 - 2023	All	Not Applicable

Condition

Customer states:

• No customer concerns, it is found during PDI or any other diagnostic work.

Workshop findings:

• The front hood noise insulation is discovered missing.

Technical Background

The absence of the front hood noise insulation is deliberate (Figure 1). The factory no longer installs the noise insulation in production.




Figure 1. Q5 without the underhood noise insulation.

© 2021 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



Technical Service Bulletin

Production Solution

The removal of the front hood noise insulation is deliberate.

Service

- 1. Do not perform any repairs. Any repairs for this concern may be denied.
- 2. Installation of a replacement insulation panel is not necessary. Instruct the customer that this condition is normal.

Warranty

This TSB is informational only and not applicable to any Audi Warranty.

Additional Information

All part and service references provided in this TSB (2061954) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.