

Special Service Message

NOTE: A Special Service Message is a formal communication issued by Jaguar and carries the same importance of a Technical Service Bulletin. An SSM is a quick method of communicating "Need To Know" information to the technical service community. SSM's may be issued in advance of a technical bulletin or may be the only communication on a given topic. All information contained in Jaguar technical communications are intended for use by trained, professional technicians with the knowledge, tools, and equipment required to complete the procedure correctly and safely. It informs the Technicians of conditions that may occur on some vehicles, or provides information that could assist in correct vehicle and diagnostic service.

SSM 75210 - X152 IMC auto day / night backlight not working as expected

Models : F-Type / X152

Engineer Shilvock Matthew

Name :

Last 08 JAN 2021 11:42:31

Modified :

Category : Diagnostic Software/Hardware

Symptom : 000101 Diagnostic Concerns

Content : X152 21MY Only.

Issue:

The Infotainment Master Control (IMC) screen does not change the backlight between day and night mode

Cause:

Instrument Cluster (IPC) software signal not transmitted to Infotainment Master Control (IMC)

Action:

Please do **not** replace or update the Infotainment Master Controller (IMC) for this concern.

JLR are aware of this issue and a Software fix will be released shortly.