

CAMPAIGN LAUNCH STATUS

SERVICE ACTIONS – VVT SOLENOID - AJ20P 4 CYL ENGINE



CSP SERVICE ACTION N481		CSP SERVICE ACTION H299	
AFFECTED MODELS	2018-2020 MY DISCOVERY SPORT; EVOQUE; DISCOVERY, RR VELAR; RANGE ROVER; RANGE ROVER SPORT. 4cyl AJ20P engines	AFFECTED MODELS	2018-2020MY F-TYPE; F-PACE; XE; XF; E-PACE 4cyl AJ20P engines
VOLUME AFFECTED	50,468 USA 5,070 CAN	VOLUME AFFECTED	36,763 USA 3,917 CAN
REPAIR	To prevent premature wear, a resulting MIL and a possible no start, all affected vehicles require the replacement of variable valve timing (VVT) solenoids on both intake an exhaust.	REPAIR	To prevent premature wear, a resulting MIL and a possible no start, all affected vehicles require the replacement of variable valve timing (VVT) solenoids on both intake an exhaust.
REPAIR TIME	Between 0.3 and 0.8 hrs based on model + drive in/out	REPAIR TIME	Between 0.2 and 0.6 hrs based on model + Drive in/out
CAMPAIGN LAUNCH	Phase 1 Oct 14 th , 2020 Phase 2 Dec 22 nd , 2020	CAMPAIGN LAUNCH	Phase 1 Oct 14 th , 2020 Phase 2 Dec 22 nd , 2020
Notes	Second and final phase now launched. Additional parts stock received in PDC's	Notes	Second and final phase now launched. Additional parts stock received in PDC's



PRINTED COPIES ARE UNCONTROLLED