

TECHNICAL TOPICS

POWERTRAIN



Fuel Gauge Drops After Filling Tank

20MY - Onward RR Evoque

Customer Voice:

- The fuel gauge drops too quickly after filling.

Technical Description:

- Changes were made to the internal geometry of the fuel tanks to mitigate the risk of this condition.
- Overall fuel consumption is not affected.
- This only affects the very top of the fuel gauge travel, normal function is noticed the rest of the gauge travel.

Status:

- Revised fuel tanks are due to be in US PDC inventory by 14-Jan-21.
- Assured fuel tanks have a serial number 26002621503A10 or newer.
- If addressing this complaint only, inspect the fuel tank serial number received from the PDC prior to installation. Any tank in inventory can be used for any other repair where the tank requires replacement.

