

TECHNICAL TOPICS

BODY/CHASSIS



Rattle Noise From Floor Console

20MY RR Evoque
20MY Discovery Sport

Customer Voice:

- A customer may report a rattle type noise from the floor console area between the front seats.

Technical Description:

- The noise may be caused by the floor console mounting bolts to the vehicle body that are becoming loose.

Status:

- SSM75211 has been published to address this concern.
- Should a customer express a concern, refer to this SSM and apply Loctite 243 to the threads of the floor console mounting bolts.

