TECHNICAL TOPICS BODY/CHASSIS





Air Conditioning Operation	16 - 21MY Range Rover, RR Sport
Customer Voice: – A customer may report the air conditioning system is not cooling properly.	
 Technical Description: This may be caused by a vehicle that is in a low state of refrigerant charge or compressor control solenoid fault. A/C compressor have been replaced and return of the compressors for analysis has found no fault with the compressor unit. 	HS2 HS2 HS2 HS2 HS2 HS2 HS2 HS2 HS2 HS2
 Status: Guided Diagnostics has been updated and symptom driven pinpoint tests are available to aid in properly diagnosing HVAC system performance concerns and should be followed to ensure a correct first time diagnosis/ repair is made. If Guided Diagnostics does not lead you to the root cause of the concern, please submit a TA case so diagnostic support can be provided. 	
	4 FL0010 GB-2016 38 @ Copyright 2017 - 2018. Jaguar Land Rover Limited.

PRINTED COPIES ARE UNCONTROLLED