

© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

**This reissue replaces all previous versions. Please destroy all previous versions.**

This bulletin supersedes TSB JTB00638NAS1/2018 dated 11 MAY 2018, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). Only refer to the electronic version of this Technical Bulletin in TOPIx.

**SECTION: 311-01**

RESCINDED - Transmission Cover Gasket Leak - RESCINDED

**AFFECTED VEHICLE RANGE:**

**E-PACE (X540)**

Model Year: 2018-2020  
VIN: Z00001-Z91414  
Assembly Plant: Graz (Austria)

**E-PACE (X540)**

Model Year: 2020  
VIN: 000001-015325  
Assembly Plant: Graz (Austria)

**MARKETS:**

NORTH AMERICA

**CONDITION SUMMARY:**

**Situation:** This bulletin has been rescinded with immediate effect. The content previously detailed within this bulletin can now be found in the TOPIx workshop manual, (see TOPIx workshop manual section 311-01: Diagnosis and Testing - Diagnostics - Vehicles with: 9HP48 9-Speed Automatic Transmission - AWD.

**Cause:** N/A

**Action:** N/A