

Classification:

BR18-009a

Reference:

January 27, 2021

Date:

2017 ARMADA; FRONT DISC BRAKE ROTOR SERVICE INFORMATION

NTB18-079a

This bulletin has been amended. See AMENDMENT HISTORY, below. Please discard previous versions of this bulletin.

APPLIED VEHICLES: 2017 Armada (Y62)

SERVICE INFORMATION

For 2017 Armada vehicles, the minimum wear thickness for the front disc brake rotors specified in the Electronic Service Manual (ESM) is incorrect.

The correct minimum wear thickness is 28.5 mm (1.122 inches).

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
November 13, 2018	NTB18-079	Original bulletin published
January 27, 2021	NTB18-079a	APPLIED VEHICLES and SERVICE INFORMATION revised

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.