## **Technical Bulletin**



# SERVICE BULLETIN

Classification: Reference: Date:

KS20-037a NTB20-073a January 28, 2021

# 2021 ROGUE AND 2020 SENTRA; INTELLIGENT KEY UNIT SERVICE INFORMATION

This bulletin has been amended. See AMENDMENT HISTORY, below.
Please discard previous versions of this bulletin.

**APPLIED VEHICLES:** 2021 Rogue (T33)

2020 Sentra (B18)

#### SERVICE INFORMATION

- When replacing the intelligent key unit (hands free module), ALWAYS replace it with a new one.
- Module configuration MUST BE performed before NATS initialization (key registration). Once NATS initialization has been performed, portions of the configuration are locked and can no longer be changed.
- When replacing the intelligent key unit, it is critical to follow the work procedure as detailed in the ESM.
  - For Rogue, go to BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT.
  - For Sentra, go to BODY EXTERIOR, DOORS, ROOF & VEHICLE SECURITY > DOOR & LOCK > BASIC INSPECTION > INTELLIGENT KEY UNIT > ADDITIONAL SERVICE WHEN REPLACING INTELLIGENT KEY UNIT.

#### NOTICE

To prevent damage to the intelligent key unit, perform module configuration **BEFORE** NATS initialization.

### **AMENDMENT HISTORY**

PUBLISHED DATE	REFERENCE	DESCRIPTION
October 14, 2020	NTB20-073	Original bulletin published
January 28, 2021	NTB20-073a	Classification number updated

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. **NOTE:** If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.