

# SS 1034867 New Cascadia Seat Belt Warning Harness Routing

---

## Applicable Vehicles

All New Cascadia

## Symptoms

The seat belt warning wiring harness can be damaged or inadvertently disconnected by a driver's foot due to its present installation beside the seat belt.

## Solution

The current solution is to extend the seat to the top of its travel, then attach the seat belt warning wiring harness to the crossbar portion of the seat assembly to keep the harness clear of foot traffic.

## **Seat Belt Wiring Harness:**



**Seat Belt Wiring Harness After Attachment:**

