

WMC1 Stop Delivery – Reworking diverse threaded connections of the vehicle's...

Version 2

WMC1 Stop Delivery – Reworking diverse threaded connections of the vehicle's suspension

**DEALERS SHOULD NOT SELL, LEASE, RENT OR LOAN ANY VEHICLES
AFFECTED BY THIS ACTION IN DEALER INVENTORY UNTIL FURTHER
NOTICE.**

Overview

There is a possibility that locknuts that were not manufactured to specification were used on diverse threaded connections of the vehicle's suspension.

As a result, the specified tightening torque may not have been met on the threaded connection and therefore cannot be guaranteed over the service life of the affected vehicles.

The locknut and the corresponding bolt at the relevant connections have to be replaced and torqued to specification.

Model line	Taycan (Y1A) 911 (992) 718 (982)
Model year	2021
Number of affected vehicles	69

Vehicle usage

Affected vehicles may only be driven for loading and unloading purposes in the transport chain. Further use is not permitted. Test drives are to be omitted.

Test instructions and remedial measures

Will be communicated once available.

Please inform all responsible dealer staff of this notification.

[WMC1 Stop Delivery VIN List.xlsx](#)

9.7 KB

(123 views)

Created by [Ryan Cooney](#) on Feb 26, 2021 11:17 PM. Last modified by [Ryan Cooney](#) on Feb 27, 2021 1:09 AM.

411 Views [Report Abuse](#)

Categories: Cayman, Taycan, Workshop Campaigns, 911 Carrera, Boxster, Stop Sale

Tags : [stop delivery](#), [taycan](#), [mj m](#), [718 \(982\)](#), [wmc1](#), [911 \(992\)](#)

- Your Groups > Edit Profile > Admin Console > Discussion >
- Your Content > Change Password > PPN Administration > Files >
- Your Places > Document >
- Collaboration >
- Document
- Blog Post >
- Poll >
- Event >
- Photo Album >
- Idea >
- Space >
- Group >

© 2021 Dr. Ing. h.c. F. Porsche AG. Legal notice. Copyright. Terms of use. Privacy Policy. Cookie Policy. [010](#)