

[Next Unread Message](#)**View Message**

Sent on	02	26	2021	Expires on	03	12	2021
From	Parts and Service Division						
Subject	Request for Parts: 2020 MDX MIL On w/ Throttle Body DTC Stored						

PRIORITY/ACTION REQUIRED

To: All Acura Service Managers/Consultants
 From: Technical Information & Support Group (formerly TRS)
 RE: Request for Parts: 2020 MDX MIL On w/ Throttle Body DTC Stored

**This message is solely directed to Acura dealership personnel; please handle accordingly.
 Print this iN message and provide a copy to the Shop Foreman and all Service Consultants.**

Background

American Honda Motor Co., Inc. (AHM) is searching for certain 2020 MDXs with a client complaint of the Malfunction Indicator Light (MIL) on with specific DTCs (see the full list below) stored. To better understand the cause of this condition, AHM would like to collect specific parts from the vehicle prior to you attempting a repair of any kind.

Qualifiers

AHM is interested ONLY if the vehicle meets the following requirements:

1. Non-Hybrid MDX only.
2. Must have one of the following DTCs stored & has NOT been cleared:
 - P2135 (TP Sensor A/B Incorrect Voltage Correlation)
 - P0123 (TP Sensor A Circuit High Voltage)
 - P0223 (TP Sensor B Circuit High Voltage)
 - P2101 (ETCS Malfunction)
 - P2176 (Throttle Actuator Control System Idle Position Not Learned)
 - P0223 (TP Sensor B Circuit High Voltage)
 - P0122 (TP Sensor A Circuit Low Voltage)
 - P0138 (Rear Secondary Heated Oxygen Sensor [Secondary HO2S (Bank 1, Sensor 2)] Circuit High Voltage)
 - P0158 (Front Secondary Heated Oxygen Sensor [Secondary HO2S (Bank 2, Sensor 2)] Circuit High Voltage)
 - P16E2 (PGM-FI-ACG LIN Communication Error)
 - P0108 (MAP Sensor Circuit High Voltage)
 - P0333 (Knock Sensor 2 [Bank 2] Circuit High Voltage)
 - P0328 (Knock Sensor 1 [Bank 1] Circuit High Voltage)
 - P0522 (Rocker Arm Oil Pressure Sensor Circuit Low Voltage)
3. Engine harness (32110) has not been replaced previously.
4. No repair attempt has been made.

Action Required

If a vehicle matching the description above comes into your dealership, please e-mail Technical Information & Support (TIS – formerly TRS) at tis@ahm.honda.com. TIS will contact you to record certain vehicle information and provide you with further instructions.

Please be sure to include the following information in your e-mail.

E-mail Title:

1. Model Year (e.g. 2020)
2. Model Name (e.g. TLX)
3. Issue (e.g. Brake Judder)
4. VIN

E-Mail Body:

1. Dealer Number
2. Your Name
3. Best Phone Number to be Reached
4. Current Mileage

Thank you.