

## **SSM 49571 - 2019-2021 Edge/Nautilus, 2020-2021 Escape/Corsair, 2021 Bronco Sport - AWD - Chatter/Shudder During Low Speed Turning Events**

Some 2019-2021 Edge/Nautilus, 2020-2021 Escape/Corsair, 2021 Bronco Sport vehicles equipped with all wheel drive (AWD) may exhibit chatter/shudder during low speed turning events due to fluid contamination. Drain and refill the rear drive unit (RDU), refer to Workshop Manual Section (WSM) 205-02. Drive for 8 km (5 miles) in stop and go conditions with right and left turns and re-evaluate. If the issue is still present, continue with WSM diagnostics. For claiming, use base (4000) causal part.

### APPLICABLE VEHICLES

2021 CAR: HD CX430N C-SUV  
2020 - 2021 CAR: TF CX483N CORSAIR  
2020 - 2021 CAR: TC CX482N ESCAPE  
2019 - 2021 CAR: DQ CD539N EDGE  
2019 - 2020 CAR: DQ CD539N EDGE  
2019 - 2021 CAR: D9 U540N MKX