

Service Alert

Mazda North American Operations
Irvine, CA 92618-2922



Subject: SQUEAK NOISE FROM FRONT BRAKES AFTER SITTING IN COLD AND MOIST WEATHER	Service Alert No.: SA-019/21
	Last Issued: 02/25/2021

APPLICABLE MODEL(S)/VINS

2011 Mazda2

DESCRIPTION

Some vehicles may exhibit a squeaking noise from front brakes when braking after sitting in cold and moist weather. Due to an increase in the resistance of the pads under cold conditions, the pads easily vibrate, causing the squeak noise.

REPAIR PROCEDURE

1. Verify customer concern.
2. Replace the guide plates with the modified ones.
3. Verify the repair.

PARTS INFORMATION

Parts Number	Description	Qty.	Notes
DFY1-33-23X	Guide Plate Set	1	For vehicles with "front pad attachment (D0YN-33-29Z)"

CONSUMER NOTICE: The information and instructions in this bulletin are intended for use by skilled technicians. Mazda technicians utilize the proper tools/equipment and take training to correctly and safely maintain Mazda vehicles. These instructions should not be performed by "do-it-yourselfers." Customers should not assume this bulletin applies to their vehicle or that their vehicle will develop the described concern. To determine if the information applies, customers should contact their nearest authorized Mazda dealership. Mazda North American Operations reserves the right to alter the specifications and contents of this bulletin without obligation or advance notice. All rights reserved. No part of this bulletin may be reproduced in any form or by any means, electronic or mechanical---including photocopying and recording and the use of any kind of information storage and retrieval system ---without permission in writing.