

SERVICE ACTION

Reference number:	SA-03-1492	Issued: 22 February, 2021
Subject:	DBX Ignition Coil Replacement	
Model(s):	DBX	
VIN Range:	Refer to the separately published list of affected Vehicle Identification Numbers (VINs)	
Applicable to:	All Dealers	
Distribute to:	After Sales Manager Executive Manager Service Manager Sales Manager	Warranty Staff Technician(s) Parts Staff

Reason for this Service Action

Aston Martin has found that some DBX vehicles have the incorrect potting compound on some engine ignition coils. Do the workshop procedure that follows to remove and install new ignition coils to correct this problem.

Workshop Procedure

1. Remove the engine ignition coils (refer to Workshop Manual Procedure 03.07.AR).
2. Install the new engine ignition coils (refer to Workshop Manual Procedure 03.07.AR).

Warranty Data

Procedure and Labour Time

Description	Labour Time
Remove and install new engine ignition coils	3.9

Part Data

Description	Part Number	Quantity
Ignition coil	MY83-SE12A366-AA	4

If you have any questions related to this document, please refer to the 'Contact Us' link on this webpage, or contact your local Dealer or After Sales Manager.

The English version of this document is written in Simplified Technical English to ASD-STE100™.