## Subject: Engineering Information - Front Door that Can Not Be Opened From the Inside or Outside

## This PI has been revised to end the need for information from the field. Please discard PIE0591.

Brand:	Model:	Model Year:		VIN:		Engine:	Transmission:
		from	to	from	to		
Chevrolet	Express	2020	2021	-	-	-	-
GMC	Savanna						

If you encounter a vehicle with the above condition, refer to SI for further diagnosis.

Version	2
Modified	Released October 16, 2020 Revised January 27, 2021 – Ended the need for further information from the field.