



# Technical Journal

TITLE:  
**Squeaking noise under front seats cushions**

<b>REF NO:</b> TJ 35817.1.0	<b>ISSUING DEPARTMENT:</b> Technical Service	<b>CAR MARKET:</b> United States and Canada	
<b>PARTNER:</b> 3 US 7510 Volvo Car USA		<b>ISSUE DATE:</b> 2020-12-22	<b>STATUS DATE:</b> 2021-01-11
<b>FUNC GROUP:</b> 8526	<b>FUNC DESC:</b> Adjustment device, assembly parts	Page 1 of 3	

“Right first time in Time”

## Attachment

File Name	File Size
TJ 35817.pdf	0.1634 MB

## DESCRIPTION:

If squeaking noise can be heard from the underside of a front seat cushion, see Service.

## CSC Customer Symptom Codes

Code	Description
ZD	Front seat/Squeak/rattle

## Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536							2019-9999		0000001-0999999	201746-999952

## SERVICE:

Apply PTFE-spray as shown on picture “TJ 35817.pdf” (2 plastic holders on each front seat).  
Raise the seat to the highest and apply from front.

Use PFTE-spray p/n 30749880.

# Technical Journal 35817.1.0



**Warranty claim info:**

To get warranty claim accepted for a job described in this TJ, please use the attached VST OP number

**VST Operation Number**

VST Operation Number	Description
99921-2	General reimbursement acc. to TJ/QB


**VEHICLE REPORT:**

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 8526.

**To view TJ attachment continue to next page. This TJ has one attachment.**



V O L V O



TJ 35817