

# **Technical Service Bulletin**

#### 48 Start/Stop steering assist is delayed

48 21 94 2057796/2 March 5, 2021. Supersedes Technical Service Bulletin Group 48 number 19-83 dated November 22, 2019 for reasons listed below.

Model(s)	Year	VIN Range	Vehicle-Specific Equipment
Q3	2019 – 2020	All	Speed related variable steering assist

### Condition

REVISION HISTORY				
Revision	Date	Purpose		
2	-	Revised <i>Production Solution</i> (Added information) Revised <i>Service</i> (Updated instructions).		
1	11/22/2019	Initial publication		

#### **Customer states:**

• There is a delay of power steering assist after the engine restarts from a Start/Stop event.

#### **Technical Background**

If the engine is off during a Start/Stop event and the brake pedal is released, the car starts to move forward in creep (without applying the throttle) but the power steering has no assist for a short period of time.

The vehicle is operating as designed.

There are no DTCs stored in the power steering control module, J500 (address word 0044).

## **Production Solution**

Improved software for MY 21

#### **Service**

This TSB replaces Pending Service Solution (PSS) TSB 2059153: *PSS 48 Start/Stop steering assist is delayed*. Proceed with Field Campaign 96H5 to improve the Start/Stop system, vehicle drivability, and power steering delay.

© 2021 Audi of America, Inc.

Page 1 of 2

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.



## **Technical Service Bulletin**



Do not replace the steering rack or any components related to the Start/Stop system.

#### Warranty

This TSB is informational only and not applicable to any Audi Warranty.

### **Additional Information**

All part and service references provided in this TSB (2057796) are subject to change and/or removal. Always check with your Parts Department and/or ETKA for the latest information and parts bulletins. Please check the Repair Manual for fasteners, bolts, nuts, and screws that require replacement during the repair.

©2021 Audi of America, Inc. All rights reserved. The information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.

© 2021 Audi of America, Inc.

All rights reserved. Information contained in this document is based on the latest information available at the time of printing and is subject to the copyright and other intellectual property rights of Audi of America, Inc., its affiliated companies and its licensors. All rights are reserved to make changes at any time without notice. No part of this document may be reproduced, stored in a retrieval system, or transmitted in any form or by any means, electronic, mechanical, photocopying, recording, or otherwise, nor may these materials be modified or reposted to other sites, without the prior expressed written permission of the publisher.