

NUMBER: 23-007-21

GROUP: 23 - Body

DATE: February 2, 2021

This bulletin is supplied as technical information only and is not an authorization for repair. No part of this publication may be reproduced, stored in a retrieval system, or transmitted, in any form or by any means, electronic, mechanical, photocopying, or otherwise, without written permission of FCA US LLC.

This bulletin supersedes Technical Service Bulletin (TSB) 23-014-20, date of issue March 11, 2020, which should be removed from your files. All revisions are highlighted with **asterisks**** and include additional discussion information.**

SUBJECT:

Split/Crack of Metal Body Side Door Check Strap

OVERVIEW:

This bulletin involves retrofitting the door check strap mounting on the body side.

MODELS:

2014 - 2020

(VF)

RAM ProMaster

NOTE: This bulletin applies to vehicles within the following markets/countries: North America.

SYMPTOM/CONDITION:

The customer may notice a metal split or crack on the body side on either the driver or passenger side of the door check strap area (Fig. 1).



Fig. 1
Check Strap Area Cracking

DISCUSSION:

****A step by step service repair is available. Refer to the detailed service procedures available in DealerConnect> Service Library>Collision Info under: 31 - Collision Information / Standard Procedure> Hinge Pillar Repair.****

POLICY:

Information Only