



Technical Journal

TITLE:

PSCM ghost codes U230057 / U112B87

REF NO: TJ 35774.2.0	ISSUING DEPARTMENT: Technical Service	CAR MARKET: United States and Canada	
PARTNER: 3 US 7510 Volvo Car USA		ISSUE DATE: 2021-02-11	STATUS DATE: 2021-02-18
FUNC GROUP: 6422	FUNC DESC: Steering gear, servo complete	Page 1 of 2	

“Right first time in Time”

Rows beginning with * are modified

Note! If using a printed copy of this Technical Journal, first check for the latest online version.

DESCRIPTION:

If workshop finds the DTC's PSCM-U230057 and PSCM-U112B87 in the vehicle, please follow the advice under Service.

(OTA) - Over The Air

(PSCM) - Power Steering Control Module

CSC Customer Symptom Codes

Code	Description
3L	Technician information/Repair information/Not for warranty use

DTC Diagnostic Trouble Codes

Control Module	Code	Fault Type
PSCM	U230057	Permanent
PSCM	U112B87	Permanent

Vehicle Type

Type	Eng	Eng Desc	Sales	Body	Gear	Steer	Model Year	Plant	Chassis range	Struc Week Range
536	ED	E400V6					2021-2021		0439208-9999999	202037-202103



SERVICE:

* There is no need to fault trace or repair these DTC's right now as long as there are no symptoms or warning messages to the customer.

* A new PSCM software was released 2021 week 04 which includes corrections to these ghost codes, previous built cars shall not be updated now, these cars will get the new software at the next regular service opportunity or via OTA.

Warranty claim info:

No warranty claim accepted for a job described in this TJ

VEHICLE REPORT:

Yes, please submit a Vehicle Report if the service solution described in this TJ has no effect. Use concern area "Vehicle Report" and sub concern area "Support not needed", use function group 6422.