

DIAGNOSTIC SOFTWARE 2021-02 RELEASE



Notice Information

Ref	17479
Posted Date:	
Posted To:	General Manager / Business Owner, General Manager / Business Owner, General Manager / Business Owner, General Manager / Business Owner, Technician, Technician, Technician, Technician, Service Leader / Advisor, Service Leader / Advisor, Service Leader / Advisor, Service Leader / Advisor, Accounts / Admin, Accounts / Admin, Accounts / Admin, Accounts / Admin
Subject:	Service/Technical

TOL NOTICE (US&CA) – February 8, 2021

TOL Ref. # 17479-SVC

DIAGNOSTIC SOFTWARE 2021-02 RELEASE

Triumph has released version 2021-02 of the diagnostic software. It is now available to download and update on your workshop PC. Please download (from the Triumph Diagnostic Software page under the Service/Technical menu) today and commence using with immediate effect.

- Please ensure all new bikes have the latest software downloaded at PDI.
- Please ensure the latest software is downloaded on all bikes being serviced.
- **PLEASE ENSURE ALL RELEVANT STAFF ARE INFORMED OF THIS UPDATE. (remember to update those returning from holidays/absence)**

Note that the In-Use Performance Ratio (IUPR) Uploader application is included from the 2020-9 update. Refer to Technical Bulletin 210 for more information.

The release notes are stored and available to download at any time from the dedicated TDT page within TOL. Below is a summary of the changes in this latest version.

1. NEW SOFTWARE FUNCTIONALITY

- Key signal detection function test added to immobilizer diagnostics for keyless models.

2. ENGINE ECM CALIBRATIONS

- None

3. CHASSIS ECM CALIBRATIONS

Updated calibrations released for:

- Tiger 850 Sport
- Tiger 900
- Tiger 900 GT
- Tiger 900 GT-LRH
- Tiger 900 GT Pro
- Tiger 900 Rally
- Tiger 900 Rally Pro

4. INSTRUMENT CALIBRATIONS

Updated calibrations released for:

- Scrambler 1200 XC
- Scrambler 1200 XE
- Trident 660
- Trident 660 LAMS

5. KEYLESS ECM CALIBRATIONS

Updated calibrations released for:

- Rocket 3 R
- Rocket 3 GT
- Rocket 3 TFC

6. CONNECTIVITY MODULE CALIBRATIONS

- None

7. SUSPENSION ECM CALIBRATIONS

- None

8. NEW ECU UNLOCK CODES

- None

9. CALIBRATION DESCRIPTION CORRECTIONS

- None

10. KNOWN ISSUES IN THIS RELEASE

- None

11. BUG FIXES

- None

If you have any additional questions, please contact Triumph Customer Support at (888) 284-6288.